



Support for the HP ProCurve BX Transceivers:

J9099B ProCurve 100-BX-D SFP-LC Transceiver

J9100B ProCurve 100-BX-U SFP-LC Transceiver

J9142B ProCurve 1000-BX-D SFP-LC Mini-GBIC

J9143B ProCurve 1000-BX-U SFP-LC Mini-GBIC

Best practice tip: After inserting a transceiver into a switch, the Mode LED will come on for two seconds while the transceiver is initialized. Do not remove the transceiver until the Mode LED has turned off. For the Switch 2600 and 2800 Series: After inserting a transceiver into a 2600 or 2800 switch, the "M" LED will come on to indicate that the mini-GBIC slot is active. Wait at least two seconds after the "M" LED comes on if you need to remove the transceiver.

Product	Minimum Software Required for 100-BX	Minimum Software Required for 1000-BX	Support Notes
Switch 1400 Series J9077A J9078A	N/A	Any software version	Mini-GBICs can be used in only the 24-port switch (not the 8-port switch). 100-BX is not supported.
Switch 1700 Series J9079A J9080A	N/A	VB.02.00	Mini-GBICs can be used in only the 24-port switch (not the 8-port switch). 100-BX is not supported.
Switch 1800 Series J9028A/J9028B J9029A	N/A	PB.03.00	Mini-GBICs can be used in only the 24-port switch (not the 8-port switch). 100-BX is not supported.
Switch 2510-24 J9019A/J9019B	Q.11.16	Q.11.16	
Switch 2510-48 J9020A	U.11.10	U.11.10	
Switch 2510G Series J9279A J9280A	Y.11.03	Y.11.03	
Switch 2600 Series J4899A/B/C J4900A/B/C J8164A J8165A J8762A	N/A	H.10.72	100-BX is not supported.

Product	Minimum Software Required for 100-BX	Minimum Software Required for 1000-BX	Support Notes
Switch 2610 Series J9085A J9086A J9087A J9088A J9089A	R.11.22	R.11.22	
Switch 2800 Series J4903A J4904A	I.10.69	I.10.69	
Switch 2810 Series J9021A J9022A	N.11.14	N.11.14	
Switch 2900 Series J9049A J9050A	T.13.45	T.13.45	
Switch 3400cl Series J4905A J4906A	N/A	N/A	BX is not supported in this product.
Switch 3500yl Series J8692A J8693A	K.13.45	K.13.45	
Switch 4100gl Series J4865A J4887A	N/A	N/A	BX is not supported in this product.
Switch 4200vl Series J8770A J8771A J8772A J8773A	L.11.16	L.11.16	100-BX is supported in <u>only</u> the J9033A 20-Port Gig-T + 4-Port SFP Module. 100-BX is not supported in the J8776A 4-Port Mini-GBIC Module.
Switch 5300xl Series J4819A J4850A	N/A	E.11.08	100-BX is not supported.
Switch 5400zl Series J8697A J8698A	K.13.45	K.13.45	
Switch 6108 J4902A	N/A	N/A	BX is not supported in this product.
Switch 6200yl-24G-mGBIC J8992A	K.13.45	K.13.45	

Product	Minimum Software Required for 100-BX	Minimum Software Required for 1000-BX	Support Notes
Switch 8100fl Series J8727A J8728A	N/A	N/A	BX is not supported in this product.
Switch 8212zl J8715A	K.13.45	K.13.45	
Switch 9300m Series J4138A J4139A J4874A	N/A	N/A	BX is not supported in this product.
Switch 9408sl J8680A	N/A	N/A	BX is not supported in this product.

Software Updates Are *Free!*

Hewlett-Packard provides free software updates on the ProCurve Web site for your switch. To access the software updates, go to the ProCurve Web site at www.procurve.com, then click on **Software updates** to go to the “ProCurve Networking software updates” page. Under **Latest software** click on **Switches** to go to the page that has the free download for your switch.

Register for Automatic Notification of Updates. From the “ProCurve Networking software updates” page, you can also register yourself to automatically receive email notice of new updates for your managed ProCurve networking products.

To determine whether you have the latest software, you can compare the software version that is available on the Web site with the version that is currently installed on your switch.

© Copyright 2008 Hewlett-Packard Company, L.P.
The information contained herein is subject to change without notice.

November 2008

